


A new drainage ditch has been dug along the north and east sides of Elmore and the 2 man pit blind has been moved one check to the east. (see diagram) This diagram also shows the location of the new Walis access extension.



A new delivery ditch from our access road off Hunter road, around the east side of the compound and continuing along the north side and running to the Johnson canal is now in place.

New drainage ditches are now in place around the southwest and southern sides of the Compound as well as along the east and north sides. (see photos and diagram)

